



	Produktion 1999		Importe 1999		Exporte 1999		Bedarf BRD 1999	
	t	TDM	t	TDM	t	TDM	t	TDM
Schraubendruckfedern	62.710	533.526	6.020	40.554	11.962	142.587	56.768	431.493
Schraubenzugfedern	13.595	125.296	650	7.184	2.380	24.288	11.865	108.192
and. SF (Drehf.,Schenk.f.)	16.016	152.137	1.990	32.624	5.297	71.300	12.709	113.461
Blattfedern kgf. (Flachfed.)	3.754	93.768	5.447	17.398	2.210	46.518	6.991	64.648
Spiralflachfedern	31.539	386.895	1.939	23.878	6.368	85.960	27.110	324.813
Tellerfedern	5.900	156.406	158	2.527	6.165	68.272	-107	90.661
and. Federn kaltgef.	24.913	343.997	4.910	38.509	5.374	86.008	24.449	296.499
davon Drahtformfedern	12.871	159.520						
davon and. Federn kgf.	12.042	184.477						
Federn aus Kupfer	2.571	86.723	36	4.363	203	15.535	2.405	75.551
<b>Kaltgef. techn. Federn gesamt</b>	<b>160.998</b>	<b>1.878.748</b>	<b>21.148</b>	<b>167.037</b>	<b>39.958</b>	<b>540.468</b>	<b>142.188</b>	<b>1.505.318</b>
Blattfedern (ohne Par.fed.)	19.579	80.207	12.134	34.052	3.836	27.045	27.877	87.214
Parabelfedern	41.386	189.105	12.003	34.555	13.447	67.972	39.942	155.688
Schraubenfedern	59.503	332.382	12.568	33.041	33.589	116.042	38.481	249.381
and. Federn warmgeformt	5.161	79.061	2.104	16.504	2.303	36.860	4.962	58.705
Stabilisatoren, ca.	40.500	200.000	4.125	21.878	10.289	52.830	34.336	169.048
Drehstabfedern, ca.	2.150	16.150	1.248	7.328	2.102	7.578	1.297	15.900
<b>Tragfedern (warm + kgf.) gesamt</b>	<b>168.279</b>	<b>896.905</b>	<b>44.182</b>	<b>147.358</b>	<b>65.567</b>	<b>308.327</b>	<b>146.895</b>	<b>735.936</b>
<b>Gesamt 1999</b>	<b>329.277</b>	<b>2.775.653</b>	<b>65.331</b>	<b>314.395</b>	<b>105.525</b>	<b>848.795</b>	<b>289.083</b>	<b>2.241.253</b>
			19,8%		32,0%		87,8%	
			von Produktion		von Produktion		von Produktion	

Quelle: Stat. BA + VDFI (Schätzung f. Stabis + Dr.st.fed.)

Kontrolle 286.627,0 2.559.503,0

Bedarf 1999.xls

13.07.01]