



	Produktion 2000		Importe 2000		Exporte 2000		Bedarf BRD 2000	
	t	TDM	t	TDM	t	TDM	t	TDM
Schraubendruckfedern	63.292	559.430	7.532	40.555	19.075	211.241	51.750	388.744
Schraubenzugfedern	14.602	137.226	738	8.331	3.245	31.449	12.095	114.108
and. SF (Drehf.,Schenk.f.)	18.083	165.171	3.194	44.877	8.443	95.845	12.834	114.203
Blattfedern kgf. (Flachfed.)	4.058	106.230	6.334	19.989	3.973	60.361	6.419	65.858
Spiralflachfedern	35.971	355.125	2.370	31.482	7.318	96.777	31.023	289.830
Tellerfedern	6.764	180.790	97	3.144	6.181	78.182	680	105.752
and. Federn kaltgef.	31.910	392.451	3.913	46.242	6.894	109.617	28.928	329.076
davon Drahtformfedern	18.284	183.525						
davon and. Federn kgf.	13.626	208.926						
Federn aus Kupfer	3.061	92.240	36	4.363	203	15.535	2.895	81.068
<b>Kaltgef. techn. Federn gesamt</b>	<b>177.741</b>	<b>1.988.663</b>	<b>24.213</b>	<b>198.983</b>	<b>55.331</b>	<b>699.007</b>	<b>146.622</b>	<b>1.488.639</b>
Blattfedern (ohne Par.fed.)	15.367	64.687	12.161	35.268	3.677	24.187	23.851	75.768
Parabelfedern	37.992	168.685	15.037	42.151	16.709	79.958	36.320	130.878
Schraubenfedern	63.117	343.217	16.682	43.635	26.141	99.005	53.658	287.847
and. Federn warmgeformt	5.840	89.540	1.677	19.818	2.955	46.979	4.562	62.379
Stabilisatoren, ca.	40.700	196.000	7.215	34.403	18.763	87.429	29.153	142.974
Drehstabfedern, ca.	2.500	17.500	757	6.112	1.322	8.472	1.935	15.140
<b>Tragfedern (warm + kgf.) gesamt</b>	<b>165.516</b>	<b>879.629</b>	<b>53.529</b>	<b>181.387</b>	<b>69.566</b>	<b>346.030</b>	<b>149.478</b>	<b>714.986</b>
<b>Gesamt 2000</b>	<b>343.256</b>	<b>2.868.291</b>	<b>77.742</b>	<b>380.370</b>	<b>124.897</b>	<b>1.045.036</b>	<b>296.101</b>	<b>2.203.625</b>
			22,6%		36,4%		86,3%	
			von Produktion		von Produktion		von Produktion	

Quelle: Stat. BA + VDFI (Schätzung f. Stabis + Dr.st.fed.)