

	Produktion 2001		Importe 2001		Exporte 2001		Bedarf BRD 2001	
	t	TDM	t	TDM	t	TDM	t	TDM
Schraubendruckfedern	69.091	639.060	7.136	56.302	25.257	251.456	50.970	443.906
Schraubenzugfedern	14.716	135.902	925	9.726	4.626	39.170	11.016	106.458
and. SF (Drehf., Schenk.f.)	17.506	164.328	3.282	44.514	5.733	79.750	15.055	129.092
Blattfedern kgf. (Flachfed.)	4.063	114.264	5.760	20.938	4.121	67.623	5.702	67.579
Spiralflachfedern	27.435	358.920	3.395	41.929	8.608	104.385	22.222	296.464
Tellerfedern	11.609	167.014	173	4.488	5.923	84.558	5.859	86.944
and. Federn kaltgef.	32.679	386.472	4.535	54.680	6.213	110.821	31.001	330.331
davon Drahtformfedern	20.043	183.113						
davon and. Federn kgf.	12.636	203.359						
Federn aus Kupfer	3.117	96.980	20	3.523	292	25.803	2.846	74.700
Kaltgef. techn. Federn gesamt	180.216	2.062.940	25.225	236.100	60.772	763.566	144.670	1.535.474
Blattfedern (ohne Par.fed.)	16.446	66.186	10.908	33.220	2.980	22.108	24.374	77.298
Parabelfedern	32.063	148.422	16.538	48.153	13.058	69.005	35.543	127.570
Schraubenfedern	41.475	228.392	14.382	37.253	47.292	147.177	8.565	118.468
and. Federn warmgeformt	5.416	87.154	1.944	23.434	2.663	47.495	4.696	63.094
Stabilisatoren, ca.	41.300	194.400	8.598	40.065	15.889	70.708	34.009	163.757
Drehstabfedern, ca.	2.300	16.000	500	3.570	1.233	5.795	1.567	13.775
Tragfedern (warm + kgf.) gesamt	139.000	740.554	52.869	185.695	83.116	362.288	108.753	563.962
Gesamt 2001	319.216	2.803.494	78.094	421.795	143.888	1.125.853	253.423	2.099.436
			24,5%		45,1%		79,4%	
			von Produktion		von Produktion		von Produktion	

Quelle: Stat. BA + VDFI (Schätzung f. Stabis + Dr.st.fed.)

Bedarf 2001.xls

24.04.2002]